CERTIFICATE OF COMPLIANCE

Certificate Number Report Reference Issue Date E323702 E323702-20210507 2021-MAY-07

Issued to:	Turck Inc. 3000 Campus Drive Minneapolis, MN 55441-2619 USA
This certificate confirms that representative samples of	MULTI-POINT INTERCONNECTION POWER CABLE ASSEMBLIES FOR INDUSTRIAL MACHINERY See Addendum Page(s) for Model(s)
	Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety:UL 2237 & CSA C22.2 No. 182.3-16, Multi-Point
Interconnection Power Cable Assemblies for Industrial
Machinery.Additional Information:See the UL Online Certifications Directory at
https://ig.ulprospector.com for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.

Bamples

Bruce Mahrenholz, Director North American Certification Program



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

CERTIFICATE OF COMPLIANCE

Certificate Number Report Reference Issue Date E323702 E323702-20210507 2021-MAY-07

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Splitters:

Model(s) VT2-M12K-M5-2F5, VT2-M12S-M4-2F4, VT2-M12T-M4-2F4, VH2-M12K-M5-2F5, VH2-M12S-M4-2F4, VH2-M12T-M4-2F4, VH3-M12K-M5-3F5, VH3-M12S-M4-3F4, VH3-M12T-M4-3F4, RSP/2RKP56PK, RSP/2RKP46PS, RSP/2RKP46PT, SH-RKP/RSP/RKP46PS, SH-RKP/RSP/RKP46PT, BH-RKP/RSP/2RKP46PS, BH-RKP/RSP/2RKP46PT

Splitters, (USL Only):

Model(s) VT2-M12L-M5-2F5, VH2-M12L-M5-2F5, VH3-M12L-M5-3F5, RSP/2RKP56PL, SH-RKP/RSP/RKP56PL, BH-RKP/RSP/2RKP56PL

Barnelly

Bruce Mahrenholz, Director North American Certification Program



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/